



Mounting Instructions for Color ring

CEJN AB Head Office
Visiting address: Rattvägen 1
SE-541 34 Skövde, Sweden

Mailing address: P.O Box 245
SE-541 25 Skövde, Sweden




Note: Max continuous temperature +125°C
Not resistant to hydraulic oil.

To be used: Heat gun, Color ring kit, components to be marked.

1. Ring will be placed in widest groove.



2. Apply hot air gun in a sweeping movement around crimp ring until it sits tight all way round.



3. Check if ring sits flush-OK.

